

In the main window

New model.....	CTRL+N
New variation model.....	CTRL+ALT+N
New restart analysis.....	CTRL+SHIFT+N
Open file.....	CTRL+O
Save file.....	CTRL+S
Open data.....	CTRL+SHIFT+O
Save data.....	CTRL+SHIFT+S
Help.....	F1
Print.....	F7
Show/hide model browser.....	F6
Switch to model browser.....	SHIFT+F6
Calculate static position.....	F9
Run dynamic simulation.....	F10
Pause dynamic simulation.....	F11
Reset.....	F12
Open results selection form.....	F5
Go to next window.....	CTRL+F6
Go to previous window.....	CTRL+SHIFT+F6
Tile windows vertically.....	F4
Tile windows horizontally.....	SHIFT+F4
Close selected window.....	CTRL+F4
Close other windows.....	CTRL+ALT+F4
Close program.....	ALT+F4

Data selection

Go to next data item or table.....	TAB
Go to previous data item or table.....	SHIFT+TAB
Go to data item or table labelled with underlined letter.....	ALT+LETTER
Move around within a table.....	← →↑↓
Select multiple cells in table.....	SHIFT + ← →↑↓
.....	SHIFT+HOME, SHIFT+END
Go to first or last column in table.....	HOME, END
Go up or down table several rows at a time.....	PGUP, PGDN

In the model browser

Switch between groups and types view.....	CTRL+ALT+G
Edit data.....	ENTER
Move selected objects.....	CTRL+M
Rename object.....	F2
Locate.....	F3
Compare.....	F8
Lock/unlock.....	CTRL+L
Hide/show.....	CTRL+H
Properties.....	ALT+ENTER
Undo.....	CTRL+Z
Redo.....	CTRL+SHIFT+Z
Cut.....	CTRL+X
Copy.....	CTRL+C
Paste.....	CTRL+V
Delete.....	DELETE
Switch to main window.....	SHIFT+F6
Close browser.....	F6

On data forms

Help.....	F1
Go to next data form.....	F6
Go to previous data form.....	SHIFT+F6
Close other data forms.....	CTRL+ALT+F4
Display data names.....	F7
Display properties report.....	ALT+ENTER
Show connections report.....	CTRL+F8
Copy form.....	CTRL+F9
Export form.....	CTRL+F10
Open calculator.....	CTRL+F12

Graph control

Use default ranges.....	CTRL+T
Zoom.....	ALT+drag, CTRL+wheel
Pan.....	SHIFT+drag

Data editing

Enter new value cell.....	Type new value
Edit current value of selected cell.....	F2
Move selected rows up or down.....	ALT + ↑↓
Move around within new data value being entered.....	← → HOME, END
Accept edit.....	ENTER
Accept edit and go to adjacent cell.....	↑↓
Cancel edit.....	ESC
Copy selected cell(s) to clipboard.....	CTRL+C
Paste from clipboard.....	CTRL+V
Fill selection from top (copy down).....	CTRL+D
Fill selection from left (copy right).....	CTRL+R
Fill selection from bottom (copy up).....	CTRL+U,
.....	CTRL+SHIFT+D
Fill selection from right (copy left).....	CTRL+L,
.....	CTRL+SHIFT+R
Insert new rows in table.....	INSERT
Delete selected rows from table.....	DELETE

Wire frame 3D view control

Show / hide local axes.....	CTRL+Y
Show / hide node axes.....	CTRL+ALT+Y
Show / hide origins.....	SHIFT+ALT+Y
Show / hide name labels.....	CTRL+SHIFT+Y
Lock/unlock selected object.....	CTRL+L
Place new object.....	SPACE or ENTER
Edit selected object.....	CTRL+F2
Undo.....	CTRL+Z
Redo.....	CTRL+SHIFT+Z
Cut selected object.....	CTRL+X
Copy selected object or 3D view if none selected.....	CTRL+C
Paste object from clipboard.....	CTRL+V
Delete selected object.....	DELETE
Measuring tape tool.....	CTRL+SHIFT+drag

3D view control

Elevation view.....	CTRL+E
Plan view.....	CTRL+P
Rotate viewpoint up.....	CTRL+ALT+↑
Rotate viewpoint down.....	CTRL+ALT+↓
Rotate viewpoint right.....	CTRL+ALT+→
Rotate viewpoint left.....	CTRL+ALT+←
Rotate viewpoint +90°.....	CTRL+Q
Rotate viewpoint -90°.....	CTRL+SHIFT+Q
Zoom in.....	CTRL+I, CTRL+wheel, ALT+drag
Zoom out.....	CTRL+SHIFT+I, CTRL+wheel,
.....	SHIFT+ALT+drag
Move view centre - mouse pan....	SHIFT+drag
Move view centre - fine.....	← →↑↓
Move view centre - coarse.....	CTRL + ← →↑↓
Edit view parameters.....	CTRL+W
Reset to default view.....	CTRL+T
Set as default view.....	CTRL+SHIFT+T
Show entire model.....	CTRL+ALT+T

Replay control

Start / stop replay.....	CTRL+R
Replay faster.....	CTRL+F
Replay slower.....	CTRL+SHIFT+F
Step forwards one frame.....	CTRL+A
Step backwards one frame.....	CTRL+B,
.....	CTRL+SHIFT+A
Set replay time.....	CTRL+M
Edit replay parameters.....	CTRL+D